

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

511
NW
1/2-1
0.802 mi.
4232 ft.

SPILL NUMBER 9812749
2701 CROPSY AVE
BROOKLYN, NY

NY LTANKS **S104619928**
N/A

Relative:
Higher

Actual:
9 ft.

LTANKS:

Name: SPILL NUMBER 9812749
Address: 2701 CROPSY AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9812749 / 2003-07-18
Facility ID: 9812749
Site ID: 318248
Spill Date: 1999-01-12
Spill Cause: Tank Overfill
Spill Source: Private Dwelling
Spill Class: B3
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: SMSANGES
Referred To: Not reported
Reported to Dept: 1999-01-16
CID: 211
Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1999-01-16
Spill Record Last Update: 2003-07-18
Spiller Name: Not reported
Spiller Company: ALMAR FUEL
Spiller Address: MCDONALD AV
Spiller County: 001
Spiller Contact: MIKE MORENO

Spiller Phone: (718) 438-6676
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 256533
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
SANGESLAND administrative closure"

Remarks: "driver overfilled tank - caller will be contacting clean up crew"

All Materials:

Site ID: 318248
Operable Unit ID: 1070011
Operable Unit: 01
Material ID: 313032
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported